



### CROSS INSTALLATION

STEP 4:  
THREAD GROUND CABLE  
THROUGH CROSS SLEEVE  
IN TOP OF SPIRE  
INSERT CROSS SLEEVE INTO  
SPIRE SLEEVE SEAL WITH  
SILICONE. CHECK FOR PLUMB.

SUPERIOR FIBERGLASS, INC.  
PO BOX 1989  
JACKSONVILLE, TEXAS 75766  
800-527-8438

COMBINATION LIFT

CL0504

PAGE  
4