



CROSS INSTALLATION

STEP 4:
THREAD GROUND CABLE
THROUGH CROSS SLEEVE
IN TOP OF SPIRE
INSERT CROSS SLEEVE INTO
SPIRE SLEEVE SEAL WITH
SILICONE. CHECK FOR PLUMB.

SUPERIOR FIBERGLASS, INC.
PO BOX 1989
JACKSONVILLE, TEXAS 75766
800-527-8438

COMBINATION LIFT

CL0504

PAGE
4